

# BASIC FORMULAS (Metric)

## Turning (Cutting Time)

### ● Cutting Time (External Turning Case 1: 1 Pass machining)


- At Constant Revolution

$$T = \frac{60 \times L}{f \times n}$$

- At Constant Cutting Speed

$$T = \frac{60 \times \pi \times L \times D_m}{1000 \times f \times V_c}$$

T : Cutting Time [second]  
 L : Cutting Length [mm]  
 f : Feed Rate [mm/rev]  
 n : Spindle Revolution [min<sup>-1</sup>]  
 D<sub>m</sub> : Workpiece Diameter [mm]  
 V<sub>c</sub> : Cutting Speed [m/min]



### ● Cutting Time (External Turning Case 2: Multi-Pass machining)


- At Constant Revolution

$$T = \frac{60 \times L}{f \times n} \times N$$

- At Constant Cutting Speed

$$T = \frac{60 \times \pi \times L \times (D_1 + D_2)}{2 \times 1000 \times f \times V_c} \times N$$

T : Cutting Time [second]  
 L : Cutting Length [mm]  
 ap : Depth Of Cut per Pass [mm]  
 f : Feed Rate [mm/rev]  
 n : Spindle Revolution [min<sup>-1</sup>]  
 D<sub>1</sub> : Max. Diameter of Workpiece [mm]  
 D<sub>2</sub> : Min. Diameter of Workpiece [mm]  
 V<sub>c</sub> : Cutting Speed [m/min]  
 N : Number of Passes = (D<sub>1</sub> · D<sub>2</sub>)/ap/2 (if it is indivisible, obtain integer by rounding up one place of decimals.)



### ● Cutting Time (Facing)


- At Constant Revolution

$$T = \frac{60 \times (D_1 - D_2)}{2 \times f \times n} \times N$$

- At Constant Cutting Speed

$$T_1 = \frac{60 \times \pi \times (D_1 + D_2 \times D_1 - D_2)}{4000 \times f \times V_c} \times N$$

T : Cutting Time [second]  
 T<sub>1</sub> : Machining Time before reaching Max. Spindle Revolution [second]  
 L : Cutting Length [mm]  
 ap : Depth Of Cut per Pass [mm]  
 f : Feed Rate [mm/rev]  
 n : Spindle Revolution [min<sup>-1</sup>]  
 D<sub>1</sub> : Max. Diameter of Workpiece [mm]  
 D<sub>2</sub> : Min. Diameter of Workpiece [mm]  
 V<sub>c</sub> : Cutting Speed [m/min]  
 N : Number of Passes = (D<sub>1</sub> · D<sub>2</sub>)/ap/2 (if it is indivisible, obtain integer by rounding up one place of decimals.)



### ● Cutting Time (Grooving)


- At Constant Revolution

$$T = \frac{60 \times (D_1 - D_2)}{2 \times f \times n} \times N$$

- At Constant Cutting Speed

$$T_1 = \frac{60 \times \pi \times (D_1 + D_2) \times (D_1 - D_2)}{4000 \times f \times V_c} \times N$$

T : Cutting Time [second]  
 T<sub>1</sub> : Machining Time before reaching Max. Spindle Revolution [second]  
 L : Cutting Length [mm]  
 f : Feed Rate [mm/rev]  
 n : Spindle Revolution [min<sup>-1</sup>]  
 D<sub>1</sub> : Max. Diameter of Workpiece [mm]  
 D<sub>2</sub> : Min. Diameter of Workpiece [mm]  
 V<sub>c</sub> : Cutting Speed [m/min]



### ● Cutting Time (Cut-Off)

- At Constant Revolution


$$T = \frac{60 \times D_1}{2 \times f \times n}$$

- At Constant Cutting Speed

$$T_1 = \frac{60 \times \pi \times (D_1 + D_3) \times (D_1 - D_3)}{4000 \times f \times V_c}$$

$$T_3 = T_1 + \frac{60 \times D_3}{2 \times f \times N_{max}}$$

T : Cutting Time [second]  
 T<sub>1</sub> : Machining Time before reaching Max. Spindle Revolution [second]  
 T<sub>3</sub> : Machining Time when reaching Max. Spindle Revolution [second]  
 f : Feed Rate [mm/rev]  
 n : Spindle Revolution [min<sup>-1</sup>]  
 n<sub>max</sub> : Max. Spindle Revolution [min<sup>-1</sup>]  
 D<sub>1</sub> : Max. Diameter of Workpiece [mm]  
 D<sub>3</sub> : Diameter when reaching Max. Spindle Revolution [mm]  
 V<sub>c</sub> : Cutting Speed [m/min]



GRADES	A
INSERTS	B
CBN & POD	C
TURNING	E
BORING	F
GROOVING	G
CUT-OFF	H
THREADING	J
SOLID END MILLS	L
MILLING	M
SPARE PARTS	P
TECHNICAL	R
INDEX	T