

# BASIC FORMULAS (Inch / Metric)

## ■ Milling (Inch)

Table Feed with  $f_1$  Compensation (inches/minute)  
 $= IPT \times N \times RPM \times f_1$

Surface Speed per Minute

$$SFM = .262 \times DIA \times RPM$$

Metal Removal Rate

$$Q = WOC \times DOC \times IPM \text{ (in/min)}$$

Revolutions per Minute

$$RPM = \frac{3.82 \times SFM}{DIA}$$

Horsepower Required at the Spindle

$$HPS = Q \times UHP$$

Feedrate (inches/minute)

$$IPM = IPT \times N \times RPM$$

Horsepower Required at the Motor

$$HPM = \frac{HPS}{EFF}$$

Feedrate (inches/tooth)

$$\text{Programmed IPT} = \frac{t_{chip \text{ Max}}}{\cos \alpha}$$

Time in Cut (seconds)

$$T = \frac{15.7 \times DIA \times LOC}{SFM \times IPR \times N}$$

or

$$T = \frac{60 \times LOC}{IPM}$$

Radial Chip Thinning for 90° Cutters

$$f_1 = \frac{1/2 \left( \frac{Dia}{Ae} \right)}{\sqrt{\left( \frac{Dia}{Ae} \right) - 1}}$$

### Definition of Terms

DIA = Cutter Diameter (Inches)

ap= Axial depth of Cut (Inches)

EFF = Machine Efficiency

f = Feedrate (See IPM, IPR and IPT)

HPM = Horsepower Required at the Motor (HP)

HPS = Horsepower Required at the Spindle (HP)

IPM = Feedrate (Inches per Minute)

IPR = Feedrate (Inches per Revolution)

IPT = Feedrate (Inches per Tooth)

$f_1$  = Cutter Compensation Factor

WOC = Width of Cut (Inches)

LOC = Length of Cut (Inches)

N = Number of Effective Teeth in Cutter

Q = Metal Removal Rate (Cubic Inches per Minute)

RPM = Revolutions per Minute

SFM = Surface Speed (Feet per Minute)

T = Time (in Seconds)

$t_{chip \text{ Max}}$  = Maximum Recommended Chip Thickness (Inches)

UHP = Unit Horsepower Factor

$\alpha$  = Lead Angle

## ■ Milling (Metric)

### ● Cutting Speed

$$Vc = \frac{\pi \times Ds \times n}{1000}$$

Vc : Cutting Speed [m/min]

Ds : End Mill Diameter [mm]

n : Spindle Revolution [min<sup>-1</sup>]



### ● Power Requirement

$$fz = \frac{Vf}{Z \times n}$$

fz : Feed Per Tooth [mm/t]

Vf : Table Feed [mm/min]

Z : Number of Inserts

n : Spindle Revolution [min<sup>-1</sup>]