

BASIC MILLING FORMULAS (Inch)





Table Feed with f_1 Compensation (inches/minute)
 $= IPT \times N \times RPM \times f_1$

Surface Speed per Minute

$$SFM = 0.262 \times DIA \times RPM$$

Revolutions per Minute

$$RPM = \frac{3.820 \times SFM}{DIA}$$

Feedrate (inches/minute)

$$IPM = IPT \times N \times RPM$$

Feedrate (inches/tooth)

$$\text{Programmed IPT} = \frac{t_{chip \text{ Max}}}{\cos \alpha}$$

Radial Chip Thinning for 90° Cutters

$$f_1 = \frac{1/2 \left(\frac{DIA}{Ae} \right)}{\sqrt{\left(\frac{DIA}{Ae} \right) - 1}}$$

Metal Removal Rate

$$Q = WOC \text{ DOC} \times IPM \text{ (in}^3\text{/min)}$$

Horsepower Required at the Spindle

$$HPS = Q \times UHP$$

Horsepower Required at the Motor

$$HPM =$$

Time in Cut (Seconds)

$$T = \frac{15.7 \times DIA \times LOC}{SFM \times IPR \times N}$$

or

$$T = \frac{60 \times LOC}{IPM}$$

Definition of Terms

DIA = Diameter of the Workpiece (Inches)

D.O.C. = Axial Depth of Cut (Inches)

EFF = Machine Efficiency

f = Feedrate (See IPM, IPR, and IPT)

HPM = Horsepower Required at the Motor (HP)

HPS = Horsepower Required at the Spindle (HP)

IPM = Feedrate (Inches per Minute)

IPR = Feedrate (Inches per Revolution)

IPT = Feedrate (Inches per Tooth)

f_1 = Cutter Compensation Factor

WOC = Width of Cut (Inches)

LOC = Length of Cut (Inches)

N = Number of Effective Teeth in Cutter

Q = Metal Removal Rate (Cubic Inches per Minute)

RPM = Revolutions per Minute

SFM = Surface Speed (Feet per Minute)

T = Time (in Seconds)

$t_{chip \text{ Max}}$ = Maximum Recommended Chip Thickness (Inches)

UHP = Unit Horsepower Factor

α = Lead Angle

GRADES	A
LINEUP / INSERTS	B
45° / 70° LEAD	C
75° LEAD	D
90° LEAD	E
HIGH FEED	F
MULTI-FUNCTION	G
SLOT MILLS	H
RADIUS / BALL-NOSE	J
OTHER APPLICATIONS	K
TOOL HOLDING	O
SPARE PARTS	P
TECHNICAL	R
INDEX	T