

Troubleshooting

Milling

Trouble			Check Item	Tool Grade			Cutting Conditions						Tool Geometry							Setting	Machine					
			Measures	Change to Harder Grade	Change to Tougher Grade	Change to More Thermal Shock Resistant Grade	Change to More Welding Resistant Grade	Vc	fz	ap	Cutter Dia. Cutting Width Review	Tool Path Review	Coolant		Insert with Chipbreaker	Relief Angle	Corner Angle	Edge Strength / Honing	Insert Number	Insert Pocket	Wiper Edge (Relief Angle) Review	Insert Runout Check	Cutter Rigidity	Workpiece / Tool Installation	Overhang Length	Power, Rigidity
													Usage of Mist	Dry												
Trouble Item																										
Edge Damage	Flank Wear Increase	Unsuitable Cutting Conditions					● ↓					●														
		Unsuitable Tool Geometry	●												● ↑		● ↓			●						
	Rake Face Wear Increase	Unsuitable Cutting Conditions					● ↓	● ↓	● ↓			●														
		Unsuitable Tool Geometry	●												● ↑	● ↑	● ↓									
	Chipping, Cracking	Unsuitable Cutting Conditions					● ↓	● ↓	● ↓	●	●															
		Unsuitable Tool Geometry		●											● ↓	● ↑	● ↑			●	●	●	●	●	●	
	Edge Breakage by Thermal Shock	Unsuitable Cutting Conditions					● ↓	● ↓	● ↓				●													
		Unsuitable Tool Geometry			●										● ↑		● ↓									
	Built-up Edge	Unsuitable Cutting Conditions					● ↑	● ↑				●														
Unsuitable Tool Geometry					●									● ↑		● ↓										
Machining Accuracy	Poor Surface Finish	Unsuitable Cutting Conditions					● ↑	● ↓	● ↓			●														
		Unsuitable Tool Geometry	●			●											● ↓	● ↓		●	●		●	●	●	
	Burr	Unsuitable Cutting Conditions					● ↓	● ↓	● ↓	●	●															
		Unsuitable Tool Geometry													● ↑	● ↓	● ↓			●						
	Workpiece Chip Off	Unsuitable Cutting Conditions					● ↓	● ↓			●						● ↑	● ↑	● ↓	● ↑		●				
		Unsuitable Tool Geometry													● ↑	● ↑	● ↓	● ↑		●						
	Poor Planeness / Parallelness	Tool and Workpiece Evacuation					● ↓	● ↓				*5 ●		●	● ↑	● ↓	● ↓	● ↓		●	●	●	●	●	●	
Others	Heavy Chattering, Vibration	Unsuitable Cutting Conditions, Installation					● ↓	*1 ● ↓	*2 ● ↓	●	*4 ●			●	● ↑	● ↓	● ↓	● ↓				●	●	●	●	
	Damaging Chips	Unsuitable Cutting Conditions					● ↑	*3 ● ↓		●		*6 ●	●													
		Unsuitable Tool Geometry												●	● ↑			● ↓	●							

*1) To prevent chattering, the higher fz may be suitable.

*2) To prevent chattering, the larger ap may be suitable.

*3) Higher fz may be suitable.

*4) Down-cut method is recommended for Helical Endmilling.

*5) If the surface is warped by cutting heat.

*6) Compressed air is recommended.

R



Technical
Information