

True Rake Angle

$$\tan T = \tan R \times \cos C + \tan A \times \sin C$$

Inclination Angle

$$\tan I = \tan A \times \cos C - \tan R \times \sin C$$


A : Axial Rake Angle A.R. [°] (-90° < A < 90°)

R : Radial Rake Angle R.R. [°] (-90° < R < 90°)

C : Approach Angle [°] (0° < C < 90°)

T : True Rake Angle [°] (-90° < T < 90°)

I : Inclination Angle [°] (-90° < I < 90°)



Ball-Nose Endmill Cutting & Revolution


$$n = \frac{1000 \times V_a}{2 \times \pi \times \sqrt{a(2r\epsilon - a\epsilon)}}$$

n : Revolution [min⁻¹]

rε : Radius of Ball-Nose Endmill (Ball Part's radius [mm])

aε : Depth Of Cut [mm]

V_a : Cutting Speed at Point "a" [m/min]



Drilling

Cutting Speed

$$V_c = \frac{\pi \times D_c \times n}{1000}$$

V_c : Cutting Speed [m/min]

D_c : Drill Diameter [mm]

n : Spindle Revolution [min⁻¹]

Feed Rate (Milling)


$$V_f = f_z \times Z \times n$$

V_f : Table Feed [mm/min]

f_z : Feed per Tooth [mm/t]

Z : Number of Insert (Number of Insert = 1)

n : Spindle Revolution [min⁻¹]



Cutting Time

$$T = \frac{60 \times L}{f \times n} = \frac{60 \times \pi \times D_c \times L}{1000 \times V_c \times f}$$

T : Cutting Time [second]

L : Drilling Depth [mm]

f : Feed Rate [mm/rev]

n : Spindle Revolution [min⁻¹]

D_c : Drill Diameter [mm]

V_c : Cutting Speed [m/min]

Power Requirement (Reference Value)

$$P_c = \frac{D_c}{20} \times \frac{V_c}{100} \times \left(1 + \left(\frac{2.5 \times f}{0.1} \right) \right)$$

P_c : Power Requirement [kw]

D_c : Drill Diameter [mm]

V_c : Cutting Speed [m/min]

f : Feed Rate [mm/rev]

R



Technical
Information