


# Recommended Cutting Conditions


## 4FESM (Shouldering)

Application	Workpiece Material	Outside Dia. Dc (mm)	ø1	ø2	ø4	ø6	ø8	ø12	ø16
 <p>Shouldering</p> <p>Depth of Cut (apxae) (mm)</p> <p>1.5Dcx0.05Dc (Dc &lt; ø3)</p> <p>1.5Dcx0.1Dc (Dc ≥ ø3)</p>	Carbon Steel SxxC	Spindle Revolution (min <sup>-1</sup> )	25,500	13,000	6,600	4,400	3,300	2,200	1,700
		Feed Rate (mm/min)	335	345	580	620	625	630	600
	Alloy Steel SCM, SNCM	Spindle Revolution (min <sup>-1</sup> )	22,000	11,000	5,600	3,700	2,800	1,900	1,400
		Feed Rate (mm/min)	290	290	395	455	455	470	460
	Pre-hardened steel NAK, 30~45HRC	Spindle Revolution (min <sup>-1</sup> )	12,000	7,200	4,200	3,000	2,200	1,500	1,100
		Feed Rate (mm/min)	105	125	150	160	160	165	140
	Stainless steel SUS	Spindle Revolution (min <sup>-1</sup> )	22,000	11,000	5,600	3,700	2,800	1,900	1,400
		Feed Rate (mm/min)	130	145	165	165	170	175	155

\* Cutting with coolant is recommended for stainless steel.

**Slotting is not recommended.**

## 4FEKM (Tough corner edge) (Shouldering)

Application	Workpiece Material	Outside Dia. Dc (mm)	ø3	ø4	ø6	ø8	ø10	ø12	ø16
 <p>Shouldering</p> <p>Depth of Cut (apxae) (mm)</p> <p>1.5Dcx0.1Dc</p>	Carbon Steel SxxC	Spindle Revolution (min <sup>-1</sup> )	10,600	8,000	5,300	4,000	3,200	2,700	2,100
		Feed Rate (mm/min)	680	690	770	770	770	770	770
	Alloy Steel SCM, SNCM	Spindle Revolution (min <sup>-1</sup> )	8,800	6,600	4,400	3,300	2,600	2,200	2,000
		Feed Rate (mm/min)	500	550	620	630	630	630	610
	Pre-hardened steel NAK, 30~45HRC	Spindle Revolution (min <sup>-1</sup> )	6,400	4,800	3,200	2,400	1,900	1,600	1,200
		Feed Rate (mm/min)	180	180	180	190	190	190	190
	Stainless steel SUS	Spindle Revolution (min <sup>-1</sup> )	8,000	6,000	4,000	3,000	2,300	2,000	1,500
		Feed Rate (mm/min)	190	200	200	200	210	210	210

\* Cutting with coolant is recommended for stainless steel.

**Slotting is not recommended.**