для заказа - kyocera@kyocera-tools.ru

KSTB...TGF




Fig.1





Fig.2



Toolholder Dimensions

Part Number	Stock	Applicable Inserts	Dimensions (inch)						Spare Parts		Fig.	Reference Machine
			ØD	L1	L2	L3	W	ØD2	Clamp Screw	Wrench		
KSTB SR16/20 TGF32	●	TGF32L..	0.866	3.323	2.250	1.875	1.1	2.0	SB-4070TRS	FT-10	1	SR16, SR20
KSTB SR32J TGF32	●		0.866	3.605	2.625	2.125	1.5	2.0	SB-4070TRS	FT-10	2	SR32J

KSTB...TT




Fig.1





Fig.2



Toolholder Dimensions

Part Number	Stock	Applicable Inserts	Dimensions (inch)						Spare Parts		Fig.	Reference Machine
			ØD	L1	L2	L3	W	ØD2	Clamp Screw	Wrench		
KSTB SR16/20 TT32	●	TT32..	0.866	3.323	2.250	1.875	1.1	2.0	SB-4070TRS	FT-10	1	SR16, SR20
KSTB SR32J TT32	●		0.866	3.605	2.625	2.125	1.5	2.0	SB-4070TRS	FT-10	2	SR32J

Note: All KSTB holders are right-hand, which require neutral or left-hand inserts

kyocera@kyocera-tools.ru
www.kyocera-tools.ru

● : U.S. Stock Standard
○ : World Express (Shipping: 7-10 Business Days)