для заказа - kyocera@kyocera-tools.ru


KQC Series




Features

1. The way to assemble holder is turn the clamping bolt 1 revolution. Tool exchange time is less than 1 minute.
2. Junction of adapter and attachment touch both taper part and face part. And repeatability is less than 2μm.
3. Applicable to Various Tools.
   - Boring Tool (Rough & Fine)
   - Face Milling (Min. Ø63, Max. Ø160 is possible)
   - Centering Tool
   - External Turning
   - Applicable to Tools with Coolant Hole

Clamping System



Adapter Side



Attachment Side

How to Use Clamping System

1. Combine flower petal of adapter side with that of attachment side and insert the attachment.
2. Turn the attachment 45 degrees until stop (clockwise direction).
3. Turn the clamping bolt attached to adapter side 1 revolution and tighten by hexagon wrench.

kyocera@kyocera-tools.ru
www.kyocera-tools.ru