для заказа - kyocera@kyocera-tools.ru

TECHNICAL

R1 - R38

GENERAL INFORMATION	**R2 - R15**
SI UNIT CONVERSION TABLE / CUTTING SYMBOLS	R2
SURFACE ROUGHNESS	R3
HEAT TREATMENT AND HARDNESS EXPRESSION	R4
VICKERS HARDNESS CONVERSION CHART	R5
MATERIAL LIST (JIS)	R6
MATERIAL CROSS REFERENCE CHART	R7
CROSS REFERENCE TABLES	**R16 - R21**
INSERT GRADES CROSS REFERENCE	R16
MOLDED CHIPBREAKER CROSS REFERENCE	R20
CERA-NOTCH CONVERSION CHART	R21
TROUBLESHOOTING	**R22 - R23**
CUTTING EDGES FIGURATION AND COUNTERMEASURES	R22
TURNING	R23
TERMS AND ANGLES OF TOOLHOLDERS	**R24 - R25**
BASIC FORMULAS (TURNING)	**R26 - R29**
TOOLING EXAMPLES OF SMALL TOOLS	**R30 - R37**
TOOLING EXAMPLES	R30
AUTOMATIC LATHE LIST OF MANUFACTURERS	R32
LIST OF INSTRUMENTS AND APPLICABLE SMALL TOOLS AND TOOLHOLDERS	R37
LEVER LOCK PARTS COMPATIBILITY	**R38**

kyocera@kyocera-tools.ru
www.kyocera-tools.ru