

Part Numbers in Alphanumeric Order

○ : NUMBER □ : LETTER

	Part Number	Page	Description	
A	V			
	VBET	○○○○(○)M%-F	B28 Insert (Turning)	
	VBET	○○○○(○)M%-FSF	B28 Insert (Turning)	
	VBET	○○○○%-FSF	B28 Insert (Turning)	
	VBET	○○○(○)(○)M%-Y	B29 Insert (Turning)	
	VBGT	○○○○(○)M%-F	B29 Insert (Turning)	
	VBGT	○○○(○)(○)M%-Y	B29 Insert (Turning)	
	VBGT	○○○○%-F	B29 Insert (Turning)	
	VBGT	○○○(○)M%-Y	B29 Insert (Turning)	
	VBGW	○○○MEF	C7 Insert (Turning) / Previous Part Number	
B	VBGW	○○○S○○○○OMES	C7 Insert (Turning)	
	VBGW	○○○(○)S○○○○OMET	C7 Insert (Turning)	
	VBGW	○○○(○)S○○○○OSET	C7 Insert (Turning)	
	VBGW	○○○(○)T○○○○OME	C7 Insert (Turning)	
	VBGW	○○○(○)T○○○○OSE	C7 Insert (Turning)	
	C	VBMT	○○○(○)	C16 Insert (Turning)
		VBMT	○○○GP	B28 Insert (Turning)
		VBMT	○○○HQ	B28 Insert (Turning)
		VBMT	○○○(○)NE	C16 Insert (Turning)
		E	VBMT	○○○(○)PP
VBMT			○○○(○)SE	C16 Insert (Turning)
VBMT			○○○(○)VF	B28 Insert (Turning)
VCGT			○○○AH	B30 Insert (Turning)
VCGT			○○○%-A3	B30 Insert (Turning)
F			VCGW	○○○○○(○)S○○○○OMET
	VCGW		○○○○○S○○○○OSET	C7 Insert (Turning)
	VCGW		○○○○○(○)T○○○○OME	C7 Insert (Turning)
	VCGW		○○○○○(○)T○○○○OSE	C7 Insert (Turning)
	VCMT		○○○○○(○)	C16 Insert (Turning)
	VCMT	○○○○○(○)HQ	B30 Insert (Turning)	
	VCMT	○○○○○(○)NE	C16 Insert (Turning)	
	VCMT	○○○○○(○)PP	B30 Insert (Turning)	
	VCMT	○○○○○(○)SE	C16 Insert (Turning)	
	VCMT	○○○○○(○)VF	B30 Insert (Turning)	
G	VNBR	○○○○-○○(○)	F31 System Tip-bars (Boring)	
	VNBR	○○○○-○○(○)NB	C21,F31 System Tip-bars (Boring)	
	VNBR	○○○○(○)(○)-○○(○)S	F30 System Tip-bars (Boring)	
	VNBTR	○○○○-○○(○)	F31 System Tip-bars (Boring)	
	VNBXR	○○○○(○)-○○(○)S	F34 System Tip-bars (Boring)	
	VNFR	○○○○-○○	G47 System Tip-bars (Grooving)	
	VNGR	○○○○-○○	G37 System Tip-bars (Grooving)	
	VNTR	○○○-○○	J15 System Tip-bars (Threading)	
	VPET	○○○○(○)(○)F%-USF	B32 Insert (Turning)	
	VPET	○○○○(○)(○)M%-F	B32 Insert (Turning)	
H	VPET	○○○○(○)(○)M%-FSF	B32 Insert (Turning)	
	VPET	○○○○(○)MF%-J	B32 Insert (Turning)	

Part Number	Page	Description
VPET	○○○○(○)(○)MF%-U	B32 Insert (Turning)
VPET	○○○○(○)(○)MF%-USF	B32 Insert (Turning)
VPET	○○○○(○)(○)M%-FSF	B32 Insert (Turning)
VPGT	○○○○CF	B31 Insert (Turning)
VPGT	○○○○(○)(○)CK	B31 Insert (Turning)
VPGT	○○○○OM-CF	B31 Insert (Turning)
VPGT	○○○○(○)(○)M-CK	B31 Insert (Turning)
VPGT	○○○○MF-GF	B31 Insert (Turning)
VPGT	○○○○MFP-GF	B31 Insert (Turning)
VPGT	○○○○MP-CF	B31 Insert (Turning)
VPGT	○○○○(○)(○)MP-CK	B31 Insert (Turning)
W		
WBET	○○○○(○)(○)M%-F	B33 Insert (Turning)
WBG	○○○○OM%-CF	B33 Insert (Turning)
WBG	○○○○OMP%-CF	B33 Insert (Turning)
WBG	○○○○(○)(○)M%-F	B33 Insert (Turning)
WBG	○○○○(○)(○)M%-F	B33 Insert (Turning)
WBGW	○○○○(○)(○)M%	B34 Insert (Turning)
WBGW	○○○○(○)(○)S○○○○○M%-SET	C8 Insert (Turning)
WBGW	○○○○(○)(○)T○○○○○M%-SE	C8 Insert (Turning)
WBMT	○○○○(○)(○)L	C16,C17 Insert (Turning)
WBMT	○○○○(○)(○)L-NE	C16,C17 Insert (Turning)
WBMT	○○○○(○)L-SE	C16,C17 Insert (Turning)
WBMT	○○○○(○)(○)M%-DP	B33 Insert (Turning)
WPGT	○○○○(○)M%-Y	B33 Insert (Turning)
WPGT	○○○(○)(○)M%-Y	B33 Insert (Turning)
WPGW	○○○(○)(○)	B34 Insert (Turning)
WPMT	○○○○○	C17 Insert (Turning)
WPMT	○○○(○)GP	B34 Insert (Turning)
WPMT	○○○(○)(○)HQ	B34 Insert (Turning)
WPMT	○○○○○NE	C17 Insert (Turning)
WPMT	○○○○○SE	C17 Insert (Turning)