

CBN & PCD TOOLS



C1 - C34

CBN TOOLS		C2 - C10
IDENTIFICATION SYSTEM		C2
HOW TO IDENTIFY EDGE PREPARATION		C2
MEGACOAT CBN		C3
APPLICATION MAPS		C4
RECOMMENDED CUTTING CONDITIONS		C4
CASE STUDIES		C5
TURNING NEGATIVE INSERTS		C6 - C13
TURNING POSITIVE INSERTS		C14 - C18
TURNING NEGATIVE INSERTS (SOLID)		C19
EXTERNAL GROOVING		C20
SOLID TIP-BARS FOR MICRO BORING	EZ Bars / Tip-Bars	C21
PCD TOOLS		C22 - C34
PCD GRADES AND FEATURES		C22
IDENTIFICATION SYSTEM		C22
RECOMMENDED CUTTING CONDITIONS		C22
TURNING NEGATIVE INSERTS		C23
TURNING POSITIVE INSERTS		C24 - C29
EXTERNAL GROOVING		C30 - C31
FOR ALUMINUM WHEEL		C31
TURNING / GROOVING		C32
SOLID TIP-BARS FOR MICRO BORING	EZ Bars	C33
	System Tip-Bars / Tip-Bars	C34