


90° Square

Negative Insert with Hole



How to read this page ➡ **B13**

<i>Part Number</i>	<i>A</i>	<i>T</i>	<i>Ød</i>
SN_32_	3/8	1/8	0.150
SN_43_	1/2	3/16	0.203

<i>Part Number</i>	A	T	Ød
SN_54_	5/8	1/4	1/4
SN_64_	3/4	1/4	5/16

	P	M	K	N	S	H	
P	● ○ ◐ ☹ ● ○ ◐	○ ○ ● ✖ ☹ ⊕	● ●				Free-Cutting Steel Carbon/Alloy Steels
M							Stainless Steel
K		●	☼ ☹ ● ●				Gray Cast Iron Nodular Cast Iron
N		○	☹ ✖ ✖				Non-ferrous Metals
S					○ ☹		HRSA Titanium Alloy
H					● ●	☹	Hard materials

Corner Radius (in)	Cermet	MEGA COAT Cermet	PVD Cermet	CVD Coated Carbide	MEGACOAT / MEGACOAT NANO	PVD Coated Carbide	DLC	Carbide	Toolholder Page	Chipbreaker Bar/rod
<i>r</i> ε	TN610 TN620 TN6010 TN6020 TN60 PV710 PV720 PV7010 PV7025 PV7005		PV90 PV7020 CA510 CA515 CA525 CA530 CA5505 CA5515 CA5525 CA5535 CA6515 CA6525 CA4505 CA4515 CA4010 CA4115 CA4120	PR1425 PR1225 PR1305 PR1310 PR1325 PR1535 PR930 PR1005 PR1025 PR1125 PDL025 KW10 SW05						
1/64	●●●●●●●●			●●●●●●●●						
1/32	●●●●●●●●			●●●●●●●●						
3/64				○●●●●●●●						
1/64	○●○●○●○●	○●●●	○●●●●●●●	●●●●●●●●						
1/32	○●○●●●○●	○●●●	●●●●●●●●	●●●●●●●●				●		
3/64	○●○●○●○●	○	○●●●●●●●	●●●●●●●●						
1/32	●●●●●●●●			●●●●●●●●				●		
3/64	●●●●●●●●			○●●●●●○●				●		
1/16	●●●●●●●●			●●●●●●●●						
1/32	○●●●●●●●	●●●●	○●●●●●●●	●●●●●●●●				●		
3/64		○	○●●●●●●●	●●●●●●●●				●		
1/16			○●○●○●○●	●●●●○●						
1/32	○●○●○●○●		○●●●	○●●●						
3/64	○●○●○●○●		○●●●	●●●●						
1/16	○●○●○●○●		●●●●	●●●●						
1/32				○●●●●●●●						
3/64				○●●●●●●●						
1/64	○●●●●●○●	○●●●○●○●		○●○●○●○●						
1/32	○●○●○●○●	○●●●○●○●		○●○●○●○●						
1/64	○●○●○●○●	○●●●○●○●	○●●●○●○●	○●○●○●○●						
1/32	○●○●○●○●	○●●●○●○●	○●●●○●○●	○●○●○●○●						
3/64	○●○●○●○●	○●●●○●○●	○●●●○●○●	○●○●○●○●						
1/16	○●○●○●○●	○●●●○●○●	○●●●○●○●	○●○●○●○●						
5/64	○●○●○●○●	○●●●○●○●	○●●●○●○●	○●○●○●○●						
3/64				○●○●○●○●						
1/16				○●○●○●○●						

