

R Technical Information

R1~R40

General Information

R2~R15

SI Unit Conversion Table / Cutting Symbol	R2
Surface Roughness	R3
Heat Treatment and Hardness Expression	R4
Vickers Hardness Conversion Chart	R5
Material List (JIS)	R6
Material Cross Reference Table	R7

Various Cross Reference Tables

R16~R23

Insert Cross Reference Table	R16
Molded Chipbreaker Cross Reference Table	R21
Milling Insert Description Cross Reference Table	R22

Trouble shooting

R24~R27

Cutting Edge Figuration and Countermeasures	R24
Turning	R25
Milling	R26
Drilling	R27

Terms and Angles of Toolholder

R28~R29

Terms and Angles of Turning Toolholder	R28
Terms and Angles of Milling Cutter	R29

Basic Formulas

R30~R33

Basic Formulas (Turning)	R30
Basic Formulas (Milling / Drilling)	R32

Tooling Examples of Small Tools

R34~R40

Tooling Examples	R34
Automatic Lathe List by Manufacturer	R36