

Clamp Sets

A	GRADES
B	INSERTS
C	CBN & PCD
E	TURNING
F	BORING
G	GROOVING
H	CUT-OFF
J	THREADING
L	SOLID END MILLS
M	MILLING
P	SPARE PARTS
R	TECHNICAL
T	INDEX

Insert Handed Spare Parts show Right-hand	Part Number	Dimension (mm)								Remarks
		A	B	C	D	E	F	G		
	CPS -5S	M5X0.8	18.0	15.0	9.5	11.00	T15	2.5	G: Indicates hexagon hole two side widths of back side of bolts	
	LGBA -16% S	M5X0.8	15.0	16.1	11.2	9.85	T15	2.0	G: Indicates hexagon hole two side widths of back side of bolts R...shows Right-hand, L...shows Left-hand	
	-22% S	M5X0.8	15.0	17.6	12.7	9.85	T15	2.0		