


(in)					(in)				
Part Number	A	T	Ød	α	Part Number	A	T	Ød	α
WB_121_	5/32	1/16	0.091	5°	WP_215_	1/4	3/32	0.110	11°
WB_1515_	3/16	3/32	0.091		WP_321_	3/8	1/8	0.173	



• Insert whose corner R(rε) dimension expressed with less than sign (e.g. <0.002, <0.004, <0.008 etc.) indicate models with minus tolerance for corner R (rε).

