

Clamps

Shape Handed Spare Parts show Right-hand	Description	Dimension (mm)						Angle (°)		Remarks	
		A	B	C	D	E	F	α	θ		
	C 17R	12.2	19.5	14.3	8.5	M8X1.25 (L-hand Thread)	-	12°	-	Clamp Screw: W8X18	
	C 20R	15.1	15.5	15.0	7.5	5.3	-	10°	-	Clamp Screw: TH8X15	
	CH -20R	13.1	15.5	14.8	7.5	5.3	-	10°	-	Clamp Screw: TH8X15	
	C 25R	13.2	15.5	15.0	7.5	5.3	-	10°	-	Clamp Screw: TH8X15	
	CE -111	35.0	25.0	10.0	8.0	3.0	10.0	-	-	Right-hand	
	-121					4.5		-	-	Left-hand	
	-131							-	-	Right-hand	
	-141							-	-	Left-hand	
	CGA -3°/L	24.0	17.66	12.0	6.2	1.9	11.0	-	-	R...shows Right-hand, L...shows Left-hand	
	-4°/L	24.0	17.66	12.0	6.2	2.9	11.0	-	-		
	-5°/L	27.5	18.66	12.0	6.2	3.9	14.5	-	-		
	CGB °/L	19.0	14.0	8.2	6.35	9.5	-	-	-	R...shows Right-hand, L...shows Left-hand	
	CGH -1°/L	25.0	22.0	8.0	6.05	3.0	5.5	-	-	R...shows Right-hand, L...shows Left-hand	
	-2°/L					5.0					
	-3°/L	29.0	23.0	8.5		6.0	6.0				
	CGIA -3R	10.7	17.0	10.5	5.2	1.8	2.0	-	-		
	-4R					2.5					
	-5R	15.7				3.5	7.0				
	CP -8TE	17.9	12.0	12.0	M8X1.25 (L-hand Thread)	10.0	-	15°	-		
	CP -8W	20.9	12.0	8.0	M8X1.25 (L-hand Thread)	13.0	-	3°	-		

P



Spare Parts