








Springs / Washers / Plugs / Nuts / Punches

Shape	Description	Dimension (mm)						Angle (°)		Remarks
		A	B	C	D	E	F	α	θ	
	SP	-5	12.0	6.7						Spring
		-6	12.0	7.7	-	-	-	-	-	
		-8	11.0	9.7						
	W	-6	11.5	1.6	6.4					Washer
		6-14	11.5	1.4	6.4	-	-	-	-	
		-8	15.5	1.6	8.4					
	WB	-5	10.0	1.0	5.3					Washer (Brass)
		-6	11.5	1.6	6.4	-	-	-	-	
		-8	15.5	1.6	8.4					
	WSP	-1	15.1	4.0	3.5	2.5	-	R1.25	-	Spacer
	GP	-1	PT1/8	7.0	-	-	5.0	-	-	Plug
		-2	PT1/4	9.0	-	-	6.0	-	-	
	WN	-1	M5X8	10.0	7.0	-	3.0	-	-	Nut
	PC	-1	60.0	8.5	-	-	-	-	-	Punch
		-2	65.0	10.0	-	-	-	-	-	
	CL63	-1	M18x1.0	36.5	12	-	6.0	-	-	Coolant Pipe (For O-Ring, see P11)

P



Spare Parts