

Automatic Lathe List by Manufacturer

Citizen Machinery

Model	Toolholder Dimensions (Gang-Type)	Number of tools	Toolholder Dimensions (Turret-Type)	Number of tools	Sleeve Dia.	Number of tools	Max. Cutting Dia.	Remarks
A12	10×10×100	5			ø19.05 / ø20		ø12	
A16	10×10×100	5			ø19.05 / ø20		ø16	
A20	12(13)×12(13)×120*1	7			ø25.4		ø20	
B12	10×10×100	5			ø19.05 / ø20		ø12	
B20	12(13)×12(13)×120	6			ø19.05 / ø20		ø20	
BL12	10×10×60~120	5			ø20(ø19.05)		ø12	
BL20	12(13)×12(13)×120	4~7			ø20(ø19.05)		ø20	
BL25	12(13)×12(13)×120	4~7			ø20(ø19.05)		ø25	
C12	10×10×120	6			ø19.05		ø12	
C16	10×10×120	6			ø19.05		ø16	
C32	16×16×130	5			ø25.4		ø32	
E16	10×10×60	20			ø19.05		ø16	
E20	16×16×90	20			ø25.4		ø20	
E25	16×16×90	20			ø25.4		ø25	
E32			16(19)×16(13)×90	20	ø25.4		ø32	
F10			10×10×60	10	ø19.05		ø10	
F12			10×10×60	10	ø19.05		ø12	
F16			10×10×60	10	ø19.05		ø16	
F20			16(19)×16(13)×90	10	ø25.4		ø20	
F25			16(19)×16(13)×90	10	ø25.4		ø25	
FL25			16×16×90	12	ø16		ø25	
FL42			16×16×90	12	ø16		ø42	
G32			16(19)×16(19)×90	10	-		ø32	
K12	12×12×100	6			ø19.05 / ø20		ø12	
K16	12×12×100	6			ø19.05 / ø20		ø16	
L10	8×8×100~130	5			ø15.875		ø10	
L16	12(10)×12(10)×130	5			ø19.05		ø16	
L20	12×12×130	5			ø19.05		ø20	
L25	16×16×130	5			ø25.4		ø25	
L32	16×16×130	5			ø25.4		ø32	
M212, M312	10×10×120	5	10×10×60	10	ø19.05		ø12	
M216, M316	10×10×120	5	10×10×60	10	ø19.05		ø16	
M220, M320	16×16×130	5	16×16×90	10	ø25.4		ø20	
M232, M332	16×16×130	5	16×16×90	10	ø25.4		ø32	
M20	13(12)×13(12)×130	5	10×10×60	10	ø19.05		ø20	
MSL12	10×10×120				-		ø12	
R04	8×8×120	5			ø15.875		ø4	
R07	8×8×120	5			ø15.875		ø7	
RL01	10(8)×10(8)×90				ø16(ø20)		ø10	
RL02	16×16×90				ø20		ø20	
RL21	10(12)×10(12)×90				ø19.05		ø35	

· This table is approved by machine manufacturers.
· Manufacturers are in no particular order.

R



Technical
Information