

## Description Index

○ : Figure, □ : Alphabet

| Description          | Page                                              | Category                                |
|----------------------|---------------------------------------------------|-----------------------------------------|
| CCGT ○○○○○○MP-CF     | <b>B45</b>                                        | Insert (Turning)                        |
| CCGT ○○○○○○%/-A3     | <b>B46</b>                                        | Insert (Turning)                        |
| CCGT ○○○○○○(○)%/-F   | <b>B47, B74</b>                                   | Insert (Turning)                        |
| CCGT ○○○○○○(○)%/-FS  | <b>B47</b>                                        | Insert (Turning)                        |
| CCGW ○○○○○○          | <b>B47, C18</b>                                   | Insert (Turning)                        |
| CCGW ○○○○○○NE        | <b>C18</b>                                        | Insert (Turning)                        |
| CCGW ○○○○○○SE        | <b>C18</b>                                        | Insert (Turning)                        |
| CCLN% □ ○○○○□-○○     | <b>D22</b>                                        | Toolholder (Turning)                    |
| CCLN% □ ○○○○□-○○A    | <b>D32</b>                                        | Toolholder (Turning)                    |
| CCLN% □ ○○○○B-○○A    | <b>F74</b>                                        | Boring Bar / Previous Description       |
| CCLN% □ ○○○○□-○○GX   | <b>D28</b>                                        | Toolholder (Turning)                    |
| CCMT ○○○○○○          | <b>B46, B74, C18</b>                              | Insert (Turning)                        |
| CCMT ○○○○○○OGK       | <b>B45, B74</b>                                   | Insert (Turning)                        |
| CCMT ○○○○○○HQ        | <b>B45, B74</b>                                   | Insert (Turning)                        |
| CCMT ○○○○○○MQ        | <b>B46</b>                                        | Insert (Turning)                        |
| CCMT ○○○○○○NE        | <b>C18</b>                                        | Insert (Turning)                        |
| CCMT ○○○○○○SE        | <b>C18</b>                                        | Insert (Turning)                        |
| CCMW ○○○○○○ME        | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○○○○○ME-T      | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○○○○○SE        | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○○○○○SE-T      | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○○○○○S○○○○○MET | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○○○○○S○○○○○SET | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○○○○○T○○○○○ME  | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○T○○○T○○○○○ME  | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○T○○○T○○○○○SE  | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○T○○○ME        | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○T○○○S2E       | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○T○○○SE        | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○T○○○SE-T      | <b>C10</b>                                        | Insert (Turning) / Previous Description |
| CCMW ○○T○○○S○○○○○MET | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○T○○○S○○○○○SET | <b>C10</b>                                        | Insert (Turning)                        |
| CCMW ○○○○○○T○○○○○SE  | <b>C10</b>                                        | Insert (Turning)                        |
| CCRN% □ ○○○○□-○○A    | <b>D32</b>                                        | Toolholder (Turning)                    |
| CDHN% □ ○○○○□-○○GX   | <b>D29</b>                                        | Toolholder (Turning)                    |
| CDJN% □ ○○○○□-○○     | <b>D23</b>                                        | Toolholder (Turning)                    |
| CDJN% □ ○○○○□-○○GX   | <b>D29</b>                                        | Toolholder (Turning)                    |
| CE-010               | <b>D22, D23, F72, P14</b>                         | Spare Parts (Clamp Set)                 |
| CE-020               | <b>D25, D26, D34, D35, P14</b>                    | Spare Parts (Clamp Set)                 |
| CE-030               | <b>D27, P14</b>                                   | Spare Parts (Clamp Set)                 |
| CE-030A              | <b>D25, D27, D32, D33, D34, D35, D36, P14</b>     | Spare Parts (Clamp Set)                 |
| CE-040               | <b>D25, D27, D35, P14</b>                         | Spare Parts (Clamp Set)                 |
| CE-111               | <b>G26, P13</b>                                   | Spare Parts (Clamp)                     |
| CE-121               | <b>G26, P13</b>                                   | Spare Parts (Clamp)                     |
| CE-131               | <b>G26, P13</b>                                   | Spare Parts (Clamp)                     |
| CE-141               | <b>G26, P13</b>                                   | Spare Parts (Clamp)                     |
| CE-220               | <b>D22, D25, P14</b>                              | Spare Parts (Clamp Set)                 |
| CE-320               | <b>F72, P14</b>                                   | Spare Parts (Clamp Set)                 |
| CE-360S              | <b>F74, P14</b>                                   | Spare Parts (Clamp Set)                 |
| CE-410               | <b>D28, D29, D30, D31, F73, P14</b>               | Spare Parts (Clamp Set)                 |
| CE-430               | <b>D29, P14</b>                                   | Spare Parts (Clamp Set)                 |
| CELN% □ ○○○○B-○○     | <b>F72</b>                                        | Boring Bar / Previous Description       |
| CELN% □ ○○○○□-○○     | <b>D23</b>                                        | Toolholder (Turning)                    |
| CGA-3% □             | <b>G17, P13</b>                                   | Spare Parts (Clamp)                     |
| CGA-4% □             | <b>G17, P13</b>                                   | Spare Parts (Clamp)                     |
| CGA-5% □             | <b>G17, P13</b>                                   | Spare Parts (Clamp)                     |
| CGB% □               | <b>G11, P13</b>                                   | Spare Parts (Clamp)                     |
| CGH-1% □             | <b>G16, G45, P13</b>                              | Spare Parts (Clamp)                     |
| CGH-2% □             | <b>G16, G45, P13</b>                              | Spare Parts (Clamp)                     |
| CGH-3% □             | <b>G16, P13</b>                                   | Spare Parts (Clamp)                     |
| CGIA-3R              | <b>G48, P13</b>                                   | Spare Parts (Clamp)                     |
| CGIA-4R              | <b>G48, P13</b>                                   | Spare Parts (Clamp)                     |
| CGIA-5R              | <b>G48, P13</b>                                   | Spare Parts (Clamp)                     |
| CH-20R               | <b>M32, M33, P13</b>                              | Spare Parts (Clamp)                     |
| CIN% □ ○○○○S-○○      | <b>J17</b>                                        | Toolholder (Threading)                  |
| CL63-1               | <b>N4, N5, N6, N7, N8, N9, N10, N11, N12, P19</b> | Spare Parts (Coolant Pipe)              |

| Description          | Page                 | Category                                |
|----------------------|----------------------|-----------------------------------------|
| CL100-1              | <b>N4, N5, N11</b>   | Spare Parts (Coolant Pipe)              |
| CNGA ○○○○○○          | <b>B17, B81, C5</b>  | Insert (Turning)                        |
| CNGA ○○○○○○ME        | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGA ○○○○○○ME-T      | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGA ○○○○○○MEW       | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGA ○○○○○○SE        | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGA ○○○○○○SE-T      | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGA ○○○○○○S○○○○○    | <b>B81, C5</b>       | Insert (Turning)                        |
| CNGA ○○○○○○S○○○○○ME  | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○S○○○○○MET | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○S○○○○○MEW | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○S○○○○○SE  | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○S○○○○○SET | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○T○○○○○    | <b>B81, C5</b>       | Insert (Turning)                        |
| CNGA ○○○○○○T○○○○○ME  | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○T○○○○○SE  | <b>C5</b>            | Insert (Turning)                        |
| CNGA ○○○○○○T-○○      | <b>B75</b>           | Insert (Turning)                        |
| CNGG ○○○○○○AH        | <b>B18</b>           | Insert (Turning)                        |
| CNGG ○○○○○○DP        | <b>B14</b>           | Insert (Turning)                        |
| CNGG ○○○○○○HQ        | <b>B14</b>           | Insert (Turning)                        |
| CNGG ○○○○○○% □       | <b>B18, B40</b>      | Insert (Turning)                        |
| CNGG ○○○○○○% □-25R   | <b>B18</b>           | Insert (Turning)                        |
| CNGG ○○○○○○% □-A3    | <b>B18</b>           | Insert (Turning)                        |
| CNGG ○○○○○○% □-S     | <b>B18, B40</b>      | Insert (Turning)                        |
| CNGG ○○○○○○Z         | <b>B18</b>           | Insert (Turning)                        |
| CNGM ○○○○○○BB○       | <b>C5</b>            | Insert (Turning) / Previous Description |
| CNGM ○○○○○○S○○○○○BB○ | <b>C5</b>            | Insert (Turning)                        |
| CNGN ○○○○○○          | <b>B81</b>           | Insert (Turning)                        |
| CNGN ○○○○○○S○○○○○    | <b>B81</b>           | Insert (Turning)                        |
| CNGN ○○○○○○T○○○○○    | <b>B81</b>           | Insert (Turning)                        |
| CNGU ○○○○○○ME% □-U   | <b>B38</b>           | Insert (Turning)                        |
| CNGU ○○○○○○MF% □-F   | <b>B38</b>           | Insert (Turning)                        |
| CNGU ○○○○○○MF% □-U   | <b>B38</b>           | Insert (Turning)                        |
| CNGU ○○○○○○MF-SK     | <b>B38</b>           | Insert (Turning)                        |
| CNGX ○○○○○○T○○○○○    | <b>B81</b>           | Insert (Turning)                        |
| CNMA ○○○○○○          | <b>B17, B40, B81</b> | Insert (Turning)                        |
| CNMA ○○○○○○S○○○○○    | <b>B81</b>           | Insert (Turning)                        |
| CNMA ○○○○○○T-○○      | <b>B81</b>           | Insert (Turning)                        |
| CNMG ○○○○○○          | <b>B16, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○AH        | <b>B18</b>           | Insert (Turning)                        |
| CNMG ○○○○○○C         | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○CJ        | <b>B14</b>           | Insert (Turning)                        |
| CNMG ○○○○○○CQ        | <b>B14, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○CS        | <b>B15, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○GC        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○GP        | <b>B14, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○GS        | <b>B15, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○GT        | <b>B15, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○GU        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○HK        | <b>B15</b>           | Insert (Turning)                        |
| CNMG ○○○○○○HQ        | <b>B14, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○HS        | <b>B15, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○HT        | <b>B15, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○HU        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○MQ        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○MS        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○MU        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○PH        | <b>B16</b>           | Insert (Turning)                        |
| CNMG ○○○○○○PS        | <b>B15</b>           | Insert (Turning)                        |
| CNMG ○○○○○○PT        | <b>B15</b>           | Insert (Turning)                        |
| CNMG ○○○○○○TK        | <b>B17</b>           | Insert (Turning)                        |
| CNMG ○○○○○○TN-V      | <b>B15</b>           | Insert (Turning)                        |
| CNMG ○○○○○○WP        | <b>B14</b>           | Insert (Turning)                        |
| CNMG ○○○○○○WQ        | <b>B14, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○XP        | <b>B16, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○XP-T      | <b>B16, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○XQ        | <b>B16, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○XS        | <b>B16, B40</b>      | Insert (Turning)                        |
| CNMG ○○○○○○ZS        | <b>B17</b>           | Insert (Turning)                        |
| CNMM ○○○○○○M         | <b>C17</b>           | Insert (Turning)                        |
| CNMM ○○○○○○M-NE      | <b>C17</b>           | Insert (Turning)                        |
| CNMM ○○○○○○M-SE      | <b>C17</b>           | Insert (Turning)                        |
| CNMM ○○○○○○PX        | <b>B16</b>           | Insert (Turning)                        |
| CNMM ○○○○○○          | <b>B81, C9</b>       | Insert (Turning)                        |
| CNMM ○○○○○○S○○○○○    | <b>C9</b>            | Insert (Turning)                        |