

Description	Page	Category
TPGW ○○○○○○ME	C13	Insert (Turning) / Previous Description
TPGW ○○○○○○ME-T	C13	Insert (Turning) / Previous Description
TPGW ○○○○○○SE	C13	Insert (Turning) / Previous Description
TPGW ○○○○○○SE-T	C13	Insert (Turning) / Previous Description
TPGW ○○○○○○S○○○○○MET	C13	Insert (Turning)
TPGW ○○○○○○S○○○○○SET	C13	Insert (Turning)
TPGW ○○○○○○T○○○○○ME	C13	Insert (Turning)
TPGW ○○○○○○T○○○○○SE	C13	Insert (Turning)
TPKN ○○○○PDFR	M12	Insert (Milling)
TPKN ○○○○PDTR	M12	Insert (Milling)
TPKR ○○○○PDER-S	M12	Insert (Milling)
TPMH ○○○○○○	C21	Insert (Turning)
TPMH ○○○○○○NE	C21	Insert (Turning)
TPMH ○○○○○○SE	C21	Insert (Turning)
TPMH ○○○○○○%-NE	C21	Insert (Turning)
TPMN ○○○○○○	B65, B77, M12	Insert (Turning) / Milling)
TPMR ○○○○PDER-H	M12	Insert (Milling)
TPMR ○○○○○○	B64, B77	Insert (Turning)
TPMR ○○○○○○DP	B64, B77	Insert (Turning)
TPMR ○○○○○○G	B64, B77	Insert (Turning)
TPMR ○○○○○○GP	B64, B77	Insert (Turning)
TPMR ○○○○○○HQ	B64, B77	Insert (Turning)
TPMT ○○○○○○GP	B61, B76	Insert (Turning)
TPMT ○○○○○○HQ	B61, B76	Insert (Turning)
TPMT ○○○○○○XP	B61, B76	Insert (Turning)
TPMT ○○○○○○XQ	B61, B76	Insert (Turning)
TS-3S	D17, P7	Spare Parts (Lock Pin)
TT 43E%L○○○M	J22	Insert (Threading)
TT ○○%L○○○	J22, J23	Insert (Threading)
TT-25	M120, P18	Spare Parts (Trox Wrench / T-shape type)
TT-30	M120, P18	Spare Parts (Trox Wrench / T-shape type)
TT-15L	M101	Spare Parts (Trox Wrench / T-shape type)
TT-25L	M38, M62, M63, P18	Spare Parts (Trox Wrench / T-shape type)
TT-20	M25, M28, P18	Spare Parts (Trox Wrench / T-shape type)
TTC-25	M26, M40, P18	Spare Parts (Trox Wrench / T-shape type)
TTX 32R○○○○(○)	J21	Insert (Threading)
TTX 32R○○○○(○)S	J21	Insert (Threading)
TWBR ○○○○○-○○○	F8	Twin Bar (Turning)
TWBTR ○○○○○-○○○	F8	Twin Bar (Turning)
TWFLG ○○○	G54	Twin Bar (Grooving)
TWFLGR ○○○	G54	Twin Bar (Grooving)

V

VBET ○○○○○○(○)M%-FSF	B66	Insert (Turning)
VBET ○○○○○○(○)%-FSF	B66	Insert (Turning)
VBGT ○○○○○○FN-Z	B66	Insert (Turning)
VBGT ○○○○○○(○)M%-F	B66	Insert (Turning)
VBGT ○○○○○○(○)M%-Y	B67	Insert (Turning)
VBGT ○○○○○○(○)%-F	B66, B77	Insert (Turning)
VBGT ○○○○○○(○)%-Y	B67, B77	Insert (Turning)
VBGW ○○○○○○ME	C13	Insert (Turning) / Previous Description
VBGW ○○○○○○ME-T	C13	Insert (Turning) / Previous Description
VBGW ○○○○○○SE	C13	Insert (Turning) / Previous Description
VBGW ○○○○○○SE-T	C13	Insert (Turning) / Previous Description
VBGW ○○○○○○S○○○○○MET	C13	Insert (Turning)
VBGW ○○○○○○S○○○○○SET	C13	Insert (Turning)
VBGW ○○○○○○T○○○○○ME	C13	Insert (Turning)
VBGW ○○○○○○T○○○○○SE	C13	Insert (Turning)
VBMT ○○○○○○	C22	Insert (Turning)
VBMT ○○○○○○GP	B66, B77	Insert (Turning)
VBMT ○○○○○○HQ	B66, B77	Insert (Turning)
VBMT ○○○○○○NE	C22	Insert (Turning)
VBMT ○○○○○○SE	C22	Insert (Turning)
VBMT ○○○○○○VF	B66, B77	Insert (Turning)
VCGT ○○○○○○	B67	Insert (Turning)
VCGT ○○○○○○AH	B67	Insert (Turning)
VCGT ○○○○○○FN-Z	B67	Insert (Turning)
VCGT ○○○○○○%-A3	B67	Insert (Turning)
VCGW ○○○○○○ME	C14	Insert (Turning) / Previous Description
VCGW ○○○○○○ME-T	C14	Insert (Turning) / Previous Description
VCGW ○○○○○○SE	C14	Insert (Turning) / Previous Description
VCGW ○○○○○○SE-T	C14	Insert (Turning) / Previous Description
VCGW ○○○○○○S○○○○○MET	C14	Insert (Turning)
VCGW ○○○○○○S○○○○○SET	C14	Insert (Turning)
VCGW ○○○○○○T○○○○○ME	C14	Insert (Turning)
VCGW ○○○○○○T○○○○○SE	C14	Insert (Turning)

VCMT ○○○○○○	C22	Insert (Turning)
VCMT ○○○○○○HQ	B67, B77	Insert (Turning)
VCMT ○○○○○○NE	C22	Insert (Turning)
VCMT ○○○○○○VF	B67, B77	Insert (Turning)
VNBR ○○○○-○○(○)	F11	System Tip-Bar (Boring)
VNBR ○○○○-○○(○)S	F10	System Tip-Bar (Boring)
VNBR ○○○○-○○(○)NB	C26, F11	System Tip-Bar (Boring)
VNBTR ○○○○-○○(○)	F11	System Tip-Bar (Boring)
VNBXR ○○○○-○○(○)S	F16	System Tip-Bar (Boring)
VNFRG ○○○○-○○	G56	System Tip-Bar (Grooving)
VNFRG ○○○○-○○NB	C26, G56	System Tip-Bar (Grooving)
VNGR ○○○○-○○	G33	System Tip-Bar (Grooving)
VNGR ○○○○-○○NB	C26, G33	System Tip-Bar (Grooving)
VNGA ○○○○○○	B34, B87, C8	Insert (Turning)
VNGA ○○○○○○ME	C8	Insert (Turning) / Previous Description
VNGA ○○○○○○ME-T	C8	Insert (Turning) / Previous Description
VNGA ○○○○○○SE	C8	Insert (Turning) / Previous Description
VNGA ○○○○○○SE-T	C8	Insert (Turning) / Previous Description
VNGA ○○○○○○S○○○○○	B87, C8	Insert (Turning)
VNGA ○○○○○○S○○○○○ME	C8	Insert (Turning)
VNGA ○○○○○○S○○○○○MET	C8	Insert (Turning)
VNGA ○○○○○○S○○○○○SE	C8	Insert (Turning)
VNGA ○○○○○○S○○○○○SET	C8	Insert (Turning)
VNGA ○○○○○○T○○○○○	B87, C8	Insert (Turning)
VNGA ○○○○○○T○○○○○ME	C8	Insert (Turning)
VNGA ○○○○○○T○○○○○SE	C8	Insert (Turning)
VNGG ○○○○○○%L	B34, B43	Insert (Turning)
VNMA ○○○○○○	B87	Insert (Turning)
VNMA ○○○○○○S○○○○○	B87	Insert (Turning)
VNMG ○○○○○○	B33, B43	Insert (Turning)
VNMG ○○○○○○DP	B33	Insert (Turning)
VNMG ○○○○○○GP	B33, B43	Insert (Turning)
VNMG ○○○○○○GU	B34	Insert (Turning)
VNMG ○○○○○○HQ	B33, B43	Insert (Turning)
VNMG ○○○○○○MQ	B34	Insert (Turning)
VNMG ○○○○○○MS	B34	Insert (Turning)
VNMG ○○○○○○MU	B34	Insert (Turning)
VNMG ○○○○○○TN-V	B33	Insert (Turning)
VNMG ○○○○○○VF	B33	Insert (Turning)
VNMG ○○○○○○XP	B33, B43	Insert (Turning)
VNMM ○○○○○○M	C17	Insert (Turning)
VNMM ○○○○○○M-NE	C17	Insert (Turning)
VNMM ○○○○○○M-SE	C17	Insert (Turning)
VNTR ○○○-○○	J27	System Tip-Bar (Threading)
VPET ○○○○○○(○)F%-USF	B69	Insert (Turning)
VPET ○○○○○○(○)M%-FSF	B69	Insert (Turning)
VPET ○○○○○○(○)MF%-USF	B69	Insert (Turning)
VPET ○○○○○○(○)RL-FSF	B69	Insert (Turning)
VPGT ○○○○○○CF	B68, B77	Insert (Turning)
VPGT ○○○○○○CK	B68	Insert (Turning)
VPGT ○○○○○○F%-U	B77	Insert (Turning)
VPGT ○○○○○○M-CF	B68	Insert (Turning)
VPGT ○○○○○○M-CK	B68	Insert (Turning)
VPGT ○○○○○○MF-GF	B68	Insert (Turning)
VPGT ○○○○○○MFP-GF	B68	Insert (Turning)
VPGT ○○○○○○MP-CF	B68	Insert (Turning)
VPGT ○○○○○○MP-CK	B68	Insert (Turning)

W

W-6	G16, G45, P19	Spare Parts (Washer)
W-8	G26, P19	Spare Parts (Washer)
W6-14	P19	Spare Parts (Washer)
W6X17	M28, P6	Spare Parts (Screw)
W6X18	M112, M113	Spare Parts (Wedge Lock Screw)
W6X20	M112, M113	Spare Parts (Wedge Lock Screw)
W8X16	M40, P6	Spare Parts (Screw)
W8X18	M41, P6	Spare Parts (Screw)
W8X21	M25, P6	Spare Parts (Wedge Lock Screw)
WB-5	F76, P19	Spare Parts (Washer)
WB-6	F76, P19	Spare Parts (Washer)
WB-8	F76, P19	Spare Parts (Washer)
WBGW ○○○○○○M%-CF	B70	Insert (Turning)
WBGW ○○○○○○(○)M%-F	B70	Insert (Turning)
WBGW ○○○○○○(○)%-F	B70, B78	Insert (Turning)
WBGW ○○○○○○MP%-CF	B70	Insert (Turning)
WBGW ○○○○○○%L	B70	Insert (Turning)
WBGW ○○○○○○%-SE	C14	Insert (Turning) / Previous Description
WBGW ○○○○○○%-SE-T	C14	Insert (Turning) / Previous Description